



## The Abbey School Access Audit

Ref No	Location	Wheelchair Entry	Wheelchair Exit	Previous Commentary	Previous Recommended Action	Updated Commentary & Recommendations	Priority	Photo Ref
1	Reception entrance	No	No	Problem: Steps	Solution: Portable ramp	Action complete	N/A	3
2	Reception entrance	No	No	Problem: Steps	Solution: Portable ramp	Action complete	N/A	4
3	External entrance/ exit to Kitchen	YES	YES	Level Entry	N/A	No action required	N/A	2
4	Exit at rear of dining room	No	No	Problem: Steps	Solution: alternative access/exit	Action complete	N/A	1
5	Entrance/ exit from dining room	No	No	Problem: Steps	Solution: alternative access/exit	Action complete	N/A	5
6	Entrance/ exit from dining room	YES	YES	Level Entry	N/A	No action required	N/A	6
7	Entrance/ exit from dining room	No	No	Problem: Steps	Solution: alternative access/exit	No action required	N/A	6
8	Exit by staff room	No	No	Problem: Steps	Solution: Portable ramp	No action required. Alternative route within travel distance.	N/A	7
9	Exit from staff room	No	No	Problem: Steps	Solution: alternative access/exit	No action required	N/A	7
10	Exit from classroom	No	No	Problem: Steps	Solution: alternative access/exit	No action required	N/A	7
11	Entrance/ exit from corridor	No	No	Problem: Steps	Solution: Portable ramp	Action to provide portable ramp	1	9
						Threshold not level. Install aco drainage	1	8



## The Abbey School Access Audit

						system and level in line with threshold.		
12	Entrance/ exit from corridor	No	No	Problem: Steps	Solution: Portable ramp	Door width is non compliant. Use alternative access	N/A	10
13	Exit/ entrance to classroom	No	No	Problem: Steps	Solution: alternative access/exit/portable ramp	Door width is non compliant. Use alternative access	N/A	11
14	Exit/ entrance to classroom	No	No	Problem: Steps	Solution: alternative access/exit/portable ramp	Door width is non compliant. Use alternative access	N/A	11
15	Entrance/ exit from Hall	No	No	Problem: Steps	Solution: alternative access/exit/portable ramp	Action to provide portable ramp	1	12
16	Exit/ entrance to changing area behind hall	No	No	Problem: Steps	Solution: Portable ramp	Access internally and externally is non-compliant. Works required to the room layout to be accessible. School to consider alternative space to be used for accessible changing room	1	N/A
17	Entrance/ exit from Hall	No	No	Problem: Steps	Solution: alternative access/exit/portable ramp	Use alternative access	N/A	13
18	Exit /entrance to hall lobby	No	No	Problem: Steps	Solution: Portable ramp	Threshold is not level. Levelling works required to hard-standing area. Install aco drainage system.	1	14
19	Exit from classroom	No	No	Problem: Steps	Solution: Portable ramp	Portable ramp provided	N/A	15
20	Front entrance	No	No	Problem: Steps	Solution: Portable ramp	Action complete	N/A	3



## The Abbey School Access Audit



21	Entrance to outside classroom	YES	YES	Level Entry	N/A	Threshold is not level.	N/A	16
22	Stairs to first floor by entrance	N/A	N/A	Non accessible to first floor	Solution: stair lift access to be provided.	Stair lift has been provided. The first floor is non-wheelchair accessible. The school is to consider installing a lift.	N/A	17
23	Change in level in corridor	N/A	N/A	Non-accessible to first floor due to steps.	Solution: Portable ramp	Portable ramp is available. The first floor is non-wheelchair accessible. The school is to consider installing a lift.	N/A	N/A
24	Entrance to dining room	N/A	N/A	Non-accessible internally.	Solution: Portable ramp	Action complete	N/A	25
25	Stairs to first floor, hall lobby	N/A	N/A	Non accessible to first floor	Solution: stair lift access to be provided.	Stair lift has been provided. The first floor is non-wheelchair accessible. The school is to consider installing a lift.	N/A	18& 19
26	Stairs by reception	N/A	N/A	Non accessible to first floor	No solution provided.	The first floor is non-wheelchair accessible. The school is to consider installing a lift.	N/A	20
27	Stairs to attic	N/A	N/A	Non accessible	No solution provided.	Area is non accessible. Alternative rooms available to staff.	N/A	21& 22
28	Access to kitchen	N/A	N/A	Non accessible	Alternative access available	No works required.	N/A	24



## The Abbey School Access Audit

Ref No	Location	Wheelchair Entry	Wheelchair Exit	Previous Commentary	Previous Recommended Action	Updated Commentary & Recommendations	Priority	Photo Ref
1	Front Door (L/H Side)	YES	YES	Problem: Heavy Door Solution: Powered Doors.	Assistance required to open door.	Door to be automatic. Power assistance to be installed.	1	27
2	Front Door (R/H Side)	YES	YES	Problem: Heavy Door Solution: Powered Doors.	Assistance required to open door.	Door to be automatic. Power assistance to be installed.	1	31
3	Music Dept. Door	YES	YES	Problem: Heavy Door Solution: Powered Doors.	Assistance required to open door.	Door to be automatic. Power assistance to be installed.	1	32
4	Hall Fire Doors	NO	NO	Problem: Step Solution: Use Alternative doors.	No room outside for a ramp.	Threshold is not level. Levelling works to paved area required and install aco drainage.	1	33 & 34
5	Classroom 1 Door	NO	YES	Problem: Step Solution: Portable Ramp.	Solution: Portable ramp.	Install portable ramp with landing.	1	30
6	Classroom 2 Door	NO	YES	Problem: Step Solution: Portable Ramp	Solution: Portable ramp.	Install portable ramp with landing.	1	29
7	Classroom 3 Door	NO	YES	Problem: Step Solution: Portable Ramp.	Solution: Portable ramp.	Install portable ramp.	1	28
8	Rear Fire Doors	NO	YES	Problem: Step.	Solution: Portable ramp.	Install portable ramp.	1	N/A
9	Stairs to Upper Level	N/A	N/A	Problem: Stairs.	Solution: Use the Lift.	No works required.	N/A	26



## The Abbey School Access Audit



Ref No	Location	Wheelchair Entry	Wheelchair Exit	Previous Commentary	Previous Recommended Action	Updated Commentary & Recommendations	Priority	Photo Ref
1	Front door and lobby	NO	NO	Problem: Steps at 3 levels not practical for ramping.	Solution alternative access available.	Front door is not level. Works to external hard-standing area to provide level threshold. Installation of aco drainage system to front of door.	1	35
2	Staircase to upper level	N/A	N/A	Non-accessible to upper level due to steps.	Installation of stair lift or use alternative on ground floor for teaching.	Fire evacuation chair has been installed however upper floors are non-accessible. School to consider use of ground floor for wheelchair users.	1	36
3	Change in level in corridor	N/A	N/A	Non-accessible to upper level.	Steps to upper floor. Install temporary ramp.	Ramp has been provided, however upper floor is not accessible.	1	37
4	Access to garden	YES	YES	Level access, small threshold.	No action provided.	Levelling works required to achieve level threshold. Installation of aco drainage system.	1	38
5	Access to/from courtyard	NO	NO	Issue relates to steps.	Action to install temporary ramp.	Temporary ramp not provided. Door threshold internally is not level. Use alternative access.	N/A	39
6	Entrance to wcs	N/A	N/A	Non-accessible to upper level.	Issue: step. Assistance required.	School to consider adapting the building and installing accessible WC.	1	49
7	Access to kitchen	NO	NO	Issue: step.	Action to install temporary ramp.	Ramp installed is non accessible. School to provide permanent	1	41



## The Abbey School Access Audit



						ramp.		
8	Access to classroom	NO	NO	Issue: Step	Action to install temporary ramp.	Temporary ramp provided.	N/A	42
9	Change in level in corridor	N/A	N/A	Non-accessible to upper level	Issue: Steps. No solution feasible.	No solution feasible.	N/A	43
10	Access to attic	N/A	N/A	Non-accessible to upper level	Steps. Stair lift not practical. Disabled access not possible.	Area not accessible for students / staff.	N/A	44
11	Temporary Hall/Dining Room	YES	YES	Ramps fitted to both main and fire exits	N/A	Site manager confirmed building is now not in use.	N/A	N/A



## The Abbey School Access Audit

Ref No	Location	Wheelchair Entry	Wheelchair Exit	Previous Commentary	Previous Recommended Action	Updated Commentary & Recommendations	Priority	Photo Ref
1	Archway door	YES	YES	Problem: Shallow Step	Assistance required to operate coded lock and to open door. Solution: Concrete lip to be formed	Complete	N/A	45
2	Fire door exit by Chapel	NO	YES	Problem: Steps & inadequate ramp which lead onto gravel, with a large step to footpath.	Use the fire exit door only when the fire alarm sounds.  Solution: Use fire exit and wait on gravel for assistance, or use alternative doors.	Complete	N/A	46
3	Old Fitness Room' Fire doors	NO	YES	Problem: Steps which lead onto gravel, with a large step to footpath.	Use the fire exit door only when the fire alarm sounds. Solution: Use fire exit and wait on gravel	Recommendation as previous action. School could look to install level hard-standing.	N/A	47
4	Gym main entrance	NO	NO	Problem: Steps	The steps are too steep and the space too small, to allow for a ramp to be built. Solution: Use other doors (Items 5 & 6)	Recommendation as previous action.	N/A	48
5	Gym changing room entrance, opp Archway door.	YES	YES	Problem: Steps	Assistance required to operate coded lock and to open door. Solution: Portable ramp.	Portable ramp provided.	N/A	49
6	Gym changing room entrance,	YES	YES		Assistance required to operate coded lock and to open door. Solution: Portable	Portable ramp provided.	N/A	50



## The Abbey School Access Audit



	by Gym office.				ramp.			
7	Gym Hall fire exit (nearest Gym Main Ent)	NO	YES	Problem: Steps in different directions.	Interim solution is to use doors at Items 5 & 6 via Item 53 Solution: Permanent ramp & safety railings.	Door threshold is not level. Recommendation to use alternative exit.	N/A	51
8	Escape from CS7	NO	NO	Problem: Stairs.	Single person width escape stairs. Solution: Exit via CS5 or await assisted escape with Evacuation chair.	Complete. Exit via CS5 or await assisted escape.	N/A	52
9	Gym Hall fire exit (nearest Rose Garden door)	NO	NO	Problem: Steps.	A notice should be put on the exit doors, informing wheelchair users to use the adjacent fire exit.  Solution: Use the other fire exit (Item 7).	Use other fire exit.	N/A	53
10	Rose garden	YES	YES	Problem: Shallow Step.	Assistance required to operate coded lock and to open door.  Solution: Concrete lip to be formed.	Works not complete. External hard standing works to create level access.	1	54
11	Centre Block South Entrance	YES	YES	Problem: Step at juncture of footpath.	Assistance required to operate coded lock and to open door.  Solution: Permanent ramp.	Level access provided.	N/A	55
12	Lecture Theatre fire exit (rear)	NO	NO	Problem: Narrow steep steps.	Solution: Use fire exits at front.	Use fire exits at front.	N/A	56





## The Abbey School Access Audit

13	Drama studio external doors	NO	YES	Problem: Steps.	Solution: Portable ramp.	Portable ramp provided.	N/A	57
14	6th form entrance	YES	YES	Problem: Steps.	Solution: Permanent ramp.	Install permanent ramp with hand railings.	1	58
15	Richards Hall corridor external doors.	YES	YES	Problem: Steps. to/from patio.	Assistance required to operate coded lock and to open door.  Solution: Permanent ramp & safety railings.	Install permanent ramp with hand railings.	1	59
16	Richards Hall fire exit (side front)	NO	NO	Problem: Steps.	Interim solution is to use doors to/from Richards Hall (Item19)  Solution: Permanent ramp.	Install permanent ramp with hand railings and fixed rail.  Interim solution is to use doors to/from Richards Hall (Item19).	3	60
17	Richards Hall Fire exit (side rear)	NO	YES	Problem: Steps to/from patio.	Interim solution is to use doors to/from Richards Hall (Item 19)  Solution: Permanent ramp & safety railings.	Install permanent ramp with hand railings and fixed rail.  Interim solution is to use doors to/from Richards Hall (Item19).	3	60
18	Richards Hall	YES	YES	Problem: None.	N/A	N/A	N/A	N/A
19	Access to stage & changing rooms from the Richards Hall.	NO	NO	Problem: Narrow steps.	A temporary stage with suitable access should be considered for performances, and/or use of the floor space.	Alternative changing area to be sought.	N/A	61



## The Abbey School Access Audit

					Solution: Alternative changing area to be sought.			
20	External access to/from Richards Hall changing rooms	NO	NO	Problem: Steps	Interim solution is to provide a alternative changing area.  Solution: Permanent ramp	Install permanent ramp with hand railings.	1	62
21	Quad	YES	YES	Problem: Steps to all doors	Assistance required to open doors.  Solution: Permanent and/or temporary ramp.	Install permanent ramp with hand railings to 1no. exit.	2	63
22	Dining room Fire exit	YES	YES	Problem: None.	Assistance required to open doors.	Level access to be provided internally.	1	64
23	Kitchen rear entrance.	YES	YES	Problem: Steps	Assistance required to operate coded lock and to open door.  Solution: Permanent ramp	Permanent ramp has been provided, however requires levelling and maintenance works	2	65
24	Centre Block North Stairwell	NO	NO	Problem: Steps	Solution: Use alternative door (Item11)	Use alternative door (Item11)	N/A	67
25	Pool corridor fire exit.	NO	YES	Problem: Steps	Solution: Permanent ramp	Install permanent ramp with hand railings.	1	68
26	Swimming Pool fire exit (rear)	NO	YES	Problem: Steps Solution: Portable ramp.	Solution: Portable ramp.	Install portable ramp.	1	66
27	Swimming Pool fire exit (side)	NO	NO	Problem: Steps & narrow door	Solution: Use alternative doors (Items 26 & 28)	Use alternative doors	N/A	N/A



## The Abbey School Access Audit



28	Swimming Pool main entrance	YES	YES	Problem: Steps	N/A	Main entrance accessible. No works required.	N/A	N/A
29	Fire exit to car park by Hardcastle Hall	NO	YES	Problem: Steps	Assistance required to open doors.  Solution: Permanent ramp	Install permanent ramp with hand railings	1	N/A
30	Science Block main entrance	YES	YES	Problem: None.	Assistance required to open door.	No action required.	N/A	69
31	Side gate to rear of school	YES	YES	Problem: None.	Assistance required to operate coded lock and to open gate.	No action required.	N/A	N/A
32	Fire exit rear science block	NO	YES	Problem: None.	Assistance required to open doors.	No action required.	N/A	N/A
33	1st floor fire exit from staff room	NO	NO	Problem: External spiral staircase.	There is currently no wheelchair access to this area  Solution: Evacuation chair required.	Evacuation chair to be provided.	1	71
34	Main reception	YES	YES	Problem: None.	Assistance required to open doors.	Assistance required to open doors.	N/A	N/A
35	Girls entrance (front)	YES	YES	Problem: None.	Assistance required to open doors.	Assistance required to open doors.	N/A	N/A
36	Girls entrance (rear)	YES	YES	Problem: None.	Assistance required to open doors.	Assistance required to open doors.	N/A	N/A
37	Girls entrance (courtyard)	YES	YES	Problem: None. Solution:	Assistance required to open doors.	Assistance required to open doors.	N/A	N/A
38	Staff entrance (courtyard)	YES	YES	Problem: None.	Assistance required to open doors.	Assistance required to open doors.	N/A	N/A



## The Abbey School Access Audit

39	Post room	NO	NO	Problem: Steps	Assistance required to open doors.  Solution: Use alternative door (Item 34)	Use alternative access.	N/A	N/A
40	Stairs to Staff rooms & Hardcastle Hall upper level.	NO	NO	Problem: Stairs	Solution: Install a lift externally at Item 30	Lift not installed. School to consider alternative rooms to be used on the ground floor.	2	N/A
41	Stairs to Dance Studio	NO	NO	Problem: Stairs	Solution: Relocate the Dance Studio	Dance Studio is non-accessible in current location.	N/A	N/A
42	Stairs to disabled toilet, nurses room & science block	YES	YES	Problem: Steps	Solution: Existing stair lift & alternative access via Item 30	Use alternative access.	N/A	N/A
43	Science Block upper levels	YES	YES	Problem: Stairs	Solution: Use existing lift	Use existing lift.	N/A	N/A
44	Stairs to Careers, Exam Office and Pool Changing Rooms	YES	YES	Problem: Steps	Solution: Use existing stair lift	Use existing stair lift.	N/A	N/A
45	Pool corridor stairs	YES	YES	Problem: Steps	Solution: Use existing stair lift	Use existing stair lift.	N/A	N/A
46	Hoist for Swimming Pool	NO	NO	Problem: No hoist	Solution: Install hoist	Install hoist.	1	N/A



## The Abbey School Access Audit

47	North staircase to Centre Block upper levels	NO	NO	Problem: Stairs	Solution: Use existing lift at item 51	Use existing lift.	N/A	N/A
48	Richards Hall Balcony	NO	NO	Problem: Stairs	Assistance required to open doors. Solution: Use ground floor seating	Use ground floor seating.	N/A	N/A
49	Stairs to upper level 6th form	NO	NO	Problem: Stairs	Solution: Use existing lift at Item 51	Use existing lift.	N/A	N/A
50	Lecture Theatre	YES	YES	Problem: Tiered levels for seating	Assistance required to open doors. Solution: Use level floor space at front.	Assistance required to open doors.	N/A	N/A
51	South staircase to Centre Block upper levels	YES	YES	Problem: Stairs	Solution: Use existing lift	Use existing lift.	N/A	N/A
52	Stairs to Food Tech	NO	NO	Problem: Steps	Solution: Relocate Food Tech	Food tech room has not been relocated. School to consider relocation or secondary food tech room.	N/A	N/A
53	Gym Changing rooms to Gym Hall.	YES	YES	Problem: Stairs	Solution: Portable ramp	Portable ramp installed.	N/A	N/A
54	All levels & areas.	YES	YES	Problem: Stairs	Solution: Use existing lift	Use existing lift.	N/A	72



## The Abbey School Access Audit

Kendall Kingscott



55	Stairs to Hardcastle Hall upper level.	NO	NO	Problem: Stairs	Solution: Install a lift externally at Item30	Area is non-accessible. Refer to item 40.	N/A	73
----	--	----	----	-----------------	---	---	-----	----



## The Abbey School Access Audit

Ref No	Location	Wheelchair Entry	Wheelchair Exit	Previous Commentary	Previous Recommended Action	Updated Commentary & Recommendations	Priority	Photo Ref
1	Main Entrance	NO	NO	N/A	N/A	Step to main entrance. External levelling required to provide level threshold. Install aco drain to threshold.	1	74
2	Room 1	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	75
3	Bathroom	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	76
4	Ground Floor Lobby (Access to stairs)	NO	NO	N/A	N/A	Door opening size is non-accessible. Consider item 8 and use for access to 1 <sup>st</sup> floor.	1	77
5	Corridor	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	78
6	Room 3	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible.	1	79



## The Abbey School Access Audit



						Installation of new frame, lining and door.		
7	Room 2	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	80
8	Lift	YES	YES	N/A	N/A	Unable to test lift. Unknown if lift is in working condition, School to assess working condition of lift. If in working condition maintenance/ servicing required.	1	82
9	Kitchen no.1	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	83
10	Kitchen no.2	NO	NO	N/A	N/A	Door opening size is non-accessible. Use kitchen no.1	1	84
11	Lounge / Dinning Room	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	85
12	Lounge Patio Doors	NO	NO	N/A	N/A	Patio doors do not provide a level threshold to the external patio	1	86





## The Abbey School Access Audit

						area. School to considering replacement of doors to allow level threshold. Installation of aco drainage system to front of doors will be required.		
13	Room 4 (Access from lounge)	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	87
14	WC (Access from lounge)	NO	NO	N/A	N/A	Bathroom is non accessible for wheelchair users. School to consider adapting the building and installing accessible WC.	1	88
15	Door Access to Stairs	NO	NO	N/A	N/A	Door opening size is non-accessible. Consider item 8 and use for access to 1 <sup>st</sup> floor.	1	89
16	Rear Entrance	NO	NO	N/A	N/A	Use alternative entrance.	N/A	90
17	Access to Bathroom	NO	NO	N/A	N/A	Door opening size is non-accessible. Due to the structural make-up of the building. Alterations to make the bathroom access are not possible. School to consider an alterative location for an accessible bathroom.	N/A	91



## The Abbey School Access Audit



18	Room 13	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	92
19	1 <sup>st</sup> Floor Lobby	NO	NO	N/A	N/A	Door opening size is non-accessible. Due to the structural make-up of the building. Alterations to create access from the landing to corridor are not possible. School to consider use of rooms accessible from lift or ground floor.	N/A	93
20	Room 12	NO	NO	N/A	N/A	Door opening size is non-accessible due to item 19. School to consider use of rooms accessible from lift or ground floor.	N/A	94
21	Room 11	NO	NO	N/A	N/A	Door opening size is non-accessible due to item 19. Adjacent access is restricted due to step. School to consider use of rooms accessible from lift or ground floor.	N/A	95
22	Lobby (Between Room 10 & 11)	NO	NO	N/A	N/A	Refer to item 21.	N/A	96
23	Door Opening to Conservatory	NO	NO	N/A	N/A	Refer to item 21.	N/A	97



## The Abbey School Access Audit



24	Conservatory External Access	NO	NO	N/A	N/A	Access to the conservatory is restricted due to step and door opening size. Due to the restriction of door thresholds installation of a ramp would not be possible.	N/A	98
25	Room 8	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	100
26	Landing (adjacent to Room 8)	NO	NO	N/A	N/A	Access is restricted due to step and door opening size. School to consider use of rooms accessible from lift or ground floor.	N/A	99 & 101 & 102
27	Landing (door to corridor)	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	103
28	Bathroom	NO	NO	N/A	N/A	Door opening size is non-accessible. Due to the structural make-up of the building. Alterations to make the bathroom access are not possible. School to consider an alternative location for an accessible bathroom.	N/A	104



## The Abbey School Access Audit



29	Room 7	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	105
30	Room 6	NO	NO	N/A	N/A	Door opening size is non-accessible. Due to the structural make-up of the building. Alterations to make the room access are not possible. School to consider alternative rooms.	N/A	106
31	Room 5	NO	NO	N/A	N/A	Door opening size is non-accessible. Due to the structural make-up of the building. Alterations to make the room access are not possible. School to consider alternative rooms.	N/A	107
32	External Stairs	NO	NO	N/A	N/A	Due to the door and staircase width size access is not possible. Alternative to provide evacuation chair to stairs in item 4.	1	108



## The Abbey School Access Audit

Ref No	Location	Wheelchair Entry	Wheelchair Exit	Previous Commentary	Previous Recommended Action	Updated Commentary & Recommendations	Priority	Photo Ref
1	Main Entrance	NO	NO	N/A	N/A	Install permanent ramp with hand railings.	1	109
2	Head of External Relations Room	NO	NO	N/A	N/A	Access not level due to door threshold. Remove threshold and install new door and lining.	1	N/A
3	Rear Entrance	NO	NO	N/A	N/A	Use alternative access.	N/A	112
4	Maintenance Room	NO	NO	N/A	N/A	Install permanent ramp with hand railings.	1	111
5	External Relations Room (External Access)	NO	NO	N/A	N/A	Install permanent ramp with hand railings. Install accessible door.	1	113
6	External WC Access	NO	NO	N/A	N/A	Use internal access.	N/A	114
7	Kitchen Breakout Space	NO	NO	N/A	N/A	Use alternative access.	N/A	115
8	Corridor (adjacent to stairs)	NO	NO	N/A	N/A	Door opening size is non-accessible. Due to the structural make-up of the building. Alterations to make the room access are not possible. School to consider alternative rooms.	N/A	116
9	Corridor (adjacent to stairs)	NO	NO	N/A	N/A	Door opening size is non-accessible. Due to the structural make-up	N/A	117 & 118



## The Abbey School Access Audit



						of the building. Alterations to make the room access are not possible. School to consider alternative rooms.		
10	Breakout space	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	119
11	Female WC	NO	NO	N/A	N/A	Door opening size is non-accessible. Given the WC is non-accessible school to consider an alternative location for an accessible bathroom.	1	120
12	Kitchen	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	121
13	Opening to Break-Out Space	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	122
14	Rest Room	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible.	1	123



## The Abbey School Access Audit



						Installation of new frame, lining and door.		
15	Opening Between Properties	NO	NO	N/A	N/A	Opening size is non-accessible. Structural alteration works are required to become accessible.	1	110
16	Marketing Room	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	N/A
17	External Relations (Internal Access)	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	N/A
18	Upper Floors	NO	NO	N/A	N/A	Upper floors non-accessible.	N/A	N/A



## The Abbey School Access Audit



Ref No	Location	Wheelchair Entry	Wheelchair Exit	Previous Commentary	Previous Recommended Action	Updated Commentary & Recommendations	Priority	Photo Ref
1	Main Entrance	NO	NO	N/A	N/A	Install permanent ramp with hand railings.	1	124
2	Rear Entrance	NO	NO	N/A	N/A	Install permanent ramp with hand railings.	1	130
3	Rear Side Entrance	NO	NO	N/A	N/A	Threshold is not level. If works stated in item 2 are considered school to use alternative access.	1	133
4	Internal Opening no.1	YES	YES	N/A	N/A	Opening accessible.	N/A	125
5	Stairs	NO	NO	N/A	N/A	Upper floors non-accessible.	N/A	128
7	Room 1 (front of property)	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	126
8	Room 2	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new frame, lining and door.	1	127
10	Room 3	NO	NO	N/A	N/A	Door opening size is non-accessible. Structural alteration works are required to become accessible. Installation of new	1	129





## The Abbey School Access Audit



						frame, lining and door.		
11	Room 4	NO	NO	N/A	N/A	Area considered storage room. School to consider alterative rooms.	N/A	134



## The Abbey School Access Audit

Ref No	Location	Wheelchair Entry	Wheelchair Exit	Previous Commentary	Previous Recommended Action	Updated Commentary & Recommendations	Priority	Photo Ref
1	Main Entrance	NO	NO	N/A	N/A	Install permanent ramp with hand railings.	1	135
2	Stairs	NO	NO	N/A	N/A	Upper floors non-accessible.	N/A	136
3	Front Entrance to Flat	YES	YES	N/A	N/A	No works.	N/A	138
4	Room 1 (Front of property)	YES	YES	N/A	N/A	No works.	N/A	139
5	Room 2	YES	YES	N/A	N/A	No works.	N/A	140
6	Lounge (access via corridor)	NO	NO	N/A	N/A	Use alternative access to lounge via Room 2.	N/A	141
7	Lobby (Access from lounge)	YES	YES	N/A	N/A	No works.	N/A	142
8	Kitchen	YES	YES	N/A	N/A	No works.	N/A	143
9	Room 3 (Rear of property)	NO	NO	N/A	N/A	Door opening size is non-accessible. Due to the structural make-up of the building. Alterations to make the room access are not possible. School to consider alternative rooms.	N/A	145



## The Abbey School Access Audit

Kendall Kingscott



10	Rear Entrance			N/A	N/A	Install permanent ramp with hand railings.	1	144
----	---------------	--	--	-----	-----	--	---	-----